



APPLICATION INSTRUCTIONS - KEIM I G PRIMER (I&F GRUND)

KEIM I.G. Primer is a nitro-collodium, colourless primer with good water vapour permeability used to obliterate staining. It is usually sufficient to apply only one coat of KEIM I.G. Primer.

For extremely strong contamination a second coat is recommended with 4 hours between coats.

KEIM I. G. Primer can be used between coats of KEIM Mineral Paint systems.

SURFACE PREPARATION

- All loose, flaking and unstable material must be identified and then thoroughly removed.
- All surfaces must be thoroughly washed down with clean cold water to remove all surface dirt and dust.
- When all surfaces are clean, sound, wind dry, dust free and free from all surface contaminants, treatment using KEIM I G Primer may proceed.

MATERIAL APPLICATION

- KEIM I. G. Primer should be applied undiluted by brush and should be left for **minimum period of 5 hours** being over coated with Keim Mineral Paints.
- Should any staining 'grin' through the first coat application of Keim paint then these areas should be coated with a two-coat application of Keim I.G. Primer, brush applied with **4 hours between coats**. After a minimum period of 5 hours decoration using Keim Mineral Paints may proceed as detailed.

For more information visit: www.keim.com/en-gb/literature